

NCC 2022 is corrected by this corrigendum as follows:

## Volume One Part D3

### D3D28 Signs on doors

**Delete (4)(b) and insert (4)(b) as follows:**

(b) For a *self-closing* door—

**FIRE SAFETY DOOR  
DO NOT OBSTRUCT  
DO NOT KEEP OPEN**

## Housing Provisions Part 13.3

### 13.3.2 External glazing — winter

**Delete the formula in (1)(b) and insert the following formula:**

$$\frac{[(A_1 \times U_1 \times BC_1 \times OC_1 \times R_{W1} \times L_{W1}) + (A_2 \times U_2 \times BC_2 \times OC_2 \times R_{W2} \times L_{W2}) + \dots]}{[(A_1 \times SHGC_1 \times E_{W1} \times R_{W1} \times BS_{W1} \times L_{W1} \times F_{W1} \times H_{W1}) + (A_2 \times SHGC_2 \times E_{W2} \times R_{W2} \times BS_{W2} \times L_{W2} \times F_{W2} \times H_{W2}) + \dots]}$$

Issued by the Australian Building Codes Board  
Version: 1.1 (replaces Version 1.0)  
Release date: 24 02 2025